



NOTAM Detail

DATE: 11/08/2019 01:02 KEYS: LOCATION: RJTT

PERIOD: [19/11/08 00:00] -[19/11/15 00:00]

SCOPE: A,E,W,AE,AW,EW

New :Issued within 24 hours !: Urgent to AIP-SUP :Linked AIP-SUP

New 071251 RJAAYNYX

(5854/19 NOTAMN

Q)RJJJ/QRTCA/IV/BO/EW/000/999/3541N13945E001

A)RJTT B)1911090400 C)1911090800

E)ALL ACFT ARE REQUESTED TO AVOID FLYING IN FLW AREA AS FAR AS POSSIBLE IN ORDER TO PREVENT AN UNSAFE CONGESTION OF ACFT AND SECURE THE VIP

1.AREA : THE IMPERIAL PALACE(INCLUDE KOKYO GAIEN NATIONAL GARDEN) (354101.68N1394515.70E)

2.EXCEPTION :

(1) ACFT ON PATROL MISSION OPERATED BY POLICE DEPARTMENT

(2) ACFT ON URGENT MISSION FOR POLICE, FIRE FIGHTING AND RESCUE

(3)ACFT UNDER ATC INSTRUCTIONS OR APPROVALS IN CONSIDERATION OF WX COND, TFC SITUATIONS OR AP/AD FOR LDG AND TKOF

(4) PRESS ACFT WITH PRIOR COORDINATION WITH POLICE (REGARDLESS OF COORDINATION, AVOID FLYING OVER THE IMPERIAL PALACE)

3.RMK: METROPOLITAN POLICE DEPARTMENT TEL:03-3581-4321(EXTENSION 55331)

F)SFC G)UNL)

Contact us | Policy



AIS JAPAN Japan Aeronautical Information Service Center



NOTAM Detail

DATE: 11/08/2019 01:03 KEYS: LOCATION: RJTT

> PERIOD: [19/11/08 00:00] -[19/11/15 00:00]

SCOPE: A,E,W,AE,AW,EW

New :Issued within 24 hours !: Urgent to AIP-SUP :Linked AIP-SUP

071251 RJAAYNYX New

(5855/19 NOTAMN

Q) RJJJ/QRTCA/IV/BO/EW/000/999/3541N13945E003

A)RJTT B)1911090800 C)1911091100

E) ALL ACFT ARE REQUESTED TO AVOID FLYING IN FLW AREA AS FAR AS POSSIBLE IN ORDER TO PREVENT AN UNSAFE CONGESTION OF ACFT AND SECURE THE VIP

1.AREA : THE IMPERIAL PALACE (INCLUDE KOKYO GAIEN NATIONAL GARDEN) AND THE AREA EXTENDS 3KM OUTSIDE FM THE OUTER EDGE OF THE IMPERIAL PALACE (INCLUDE KOKYO GAIEN NATIONAL GARDEN) (354101.68N1394515.70E)

2.EXCEPTION:

- (1) ACFT ON PATROL MISSION OPERATED BY POLICE DEPARTMENT
- (2) ACFT ON URGENT MISSION FOR POLICE, FIRE FIGHTING AND RESCUE
- (3) ACFT UNDER ATC INSTRUCTIONS OR APPROVALS IN CONSIDERATION OF WX COND, TFC SITUATIONS OR AP/AD FOR LDG AND TKOF
- (4) PRESS ACFT WITH PRIOR COORDINATION WITH POLICE (REGARDLESS OF COORDINATION, AVOID FLYING OVER THE IMPERIAL PALACE)

3.RMK : METROPOLITAN POLICE DEPARTMENT TEL:03-3581-4321 (EXTENSION 55331)

F) SFC G) UNL)

Contact us | Policy



AIS JAPAN Japan Aeronautical Information Service Center



NOTAM Detail

DATE: 11/08/2019 01:03 KEYS: LOCATION: RJTT

> [19/11/08 00:00] -[19/11/15 00:00] PERIOD:

SCOPE: A,E,W,AE,AW,EW

New :Issued within 24 hours !: Urgent to AIP-SUP :Linked AIP-SUP

New

071251 RJAAYNYX (5856/19 NOTAMN

Q) RJJJ/QRTCA/IV/BO/EW/000/999/3541N13944E004

A)RJTT B)1911100500 C)1911100730

E) ALL ACFT ARE REQUESTED TO AVOID FLYING IN FLW AREA AS FAR AS POSSIBLE IN ORDER TO PREVENT AN UNSAFE CONGESTION OF ACFT AND SECURE

THE VIP

1.AREA:

(1) THE IMPERIAL PALACE AND THE AREA EXTENDS 3KM OUTSIDE FM THE OUTER EDGE OF THE IMPERIAL PALACE (354101.68N1394515.70E)

(2) AKASAKAGOYOCHI AND THE AREA EXTENDS 3KM OUTSIDE FM THE OUTER EDGE OF AKASAKAGOYOCHI (354036.89N1394338.37E)

(3) WI 3KM BOTH SIDE ALONG FLW ROAD (FM THE IMPERIAL PALACE TO AKASAKAGOYOCHI)

A) UCHIBORI STREET

KOKYO SEIMON - NIJUBASHIMAE - IWAIDABASHI - SAKURADAMON -KOKKAIMAE

B) PREFECTURAL ROAD 412

KOKKAIMAE - KOKKAISEIMONMAE - KENSEIKINENKANMAE - HIRAKAWACHO

C) NATIONAL ROUTE 246

HIRAKAWACHO - AKASAKAMITSUKE - AOYAMAITCHOME

D) PREFECTURAL ROAD 319

AOYAMAITCHOME - GONDAWARA

E) PREFECTURAL ROAD 414

GONDAWARA - AKASAKAGOSHO SEIMON

2.EXCEPTION :

(1) ACFT ON PATROL MISSION OPERATED BY POLICE DEPARTMENT

(2) ACFT ON URGENT MISSION FOR POLICE, FIRE FIGHTING AND RESCUE

(3)ACFT UNDER ATC INSTRUCTIONS OR APPROVALS IN CONSIDERATION OF WX COND, TFC SITUATIONS OR AP/AD FOR LDG AND TKOF

(4) PRESS ACFT WITH PRIOR COORDINATION WITH POLICE (REGARDLESS OF COORDINATION, AVOID FLYING OVER THE IMPERIAL PALACE, AKASAKAGOYOCHI, NOTED ABV ROAD)

3.RMK : METROPOLITAN POLICE DEPARTMENT TEL:03-3581-4321 (EXTENSION 55331)

F) SFC G) UNL)

Contact us | Policy







NOTAM Detail

DATE: 11/08/2019 01:04 KEYS: LOCATION: RJTT

> PERIOD: [19/11/08 00:00] -[19/11/15 00:00]

SCOPE: A,E,W,AE,AW,EW

New :Issued within 24 hours !: Urgent to AIP-SUP :Linked AIP-SUP

071251 RJAAYNYX New

(5857/19 NOTAMN

Q) RJJJ/QRTCA/IV/BO/EW/000/999/3541N13945E003

A)RJTT B)1911140800 C)1911142000

E) ALL ACFT ARE REQUESTED TO AVOID FLYING IN FLW AREA AS FAR AS POSSIBLE IN ORDER TO PREVENT AN UNSAFE CONGESTION OF ACFT AND SECURE THE VIP

1.AREA: THE IMPERIAL PALACE AND THE AREA EXTENDS 3KM OUTSIDE FM THE OUTER EDGE OF THE IMPERIAL PALACE (354101.68N1394515.70E)

2.EXCEPTION :

(1) ACFT ON PATROL MISSION OPERATED BY POLICE DEPARTMENT

(2) ACFT ON URGENT MISSION FOR POLICE, FIRE FIGHTING AND RESCUE

(3) ACFT UNDER ATC INSTRUCTIONS OR APPROVALS IN CONSIDERATION OF WX COND, TFC SITUATIONS OR AP/AD FOR LDG AND TKOF

(4) PRESS ACFT WITH PRIOR COORDINATION WITH POLICE (REGARDLESS OF COORDINATION, AVOID FLYING OVER THE IMPERIAL PALACE)

3.RMK : METROPOLITAN POLICE DEPARTMENT TEL:03-3581-4321 (EXTENSION 55331)

F)SFC G)UNL)

Contact us | Policy

